

序号	委托单位	报告编号	检测日期	检测结论	现场检测照片	备注
1	邹平梁邹矿业有限公司	QAJC4-BG-GSS-0447-2023	2023年9月14日	合格	 A photograph showing a worker in a red safety uniform and helmet operating a piece of industrial equipment in a laboratory or testing facility. A safety sign with the Chinese characters '注意安全' (Pay Attention to Safety) is visible on the wall in the background.	/