

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
1	自卸汽车	QAJC4-BG-ZXQC-0546-2025	2025 年 10 月 29 日	合格		/
2	自卸汽车	QAJC4-BG-ZXQC-0547-2025	2025 年 10 月 29 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
3	空压机	QAJC4-BG-KYJ-0185-2025	2025 年 10 月 29 日	合格	 工程记录 拍摄时间: 2025.10.29 地点: 临沭县·国家电网(朱仓供电所) 今日水印 相机 真实可信 MO KZGJHDPHPCYCE	/
4	空压机	QAJC4-BG-KYJ-0186-2025	2025 年 10 月 29 日	合格	 工程记录 拍摄时间: 2025.10.29 地点: 临沭县·临沭宝川宏原矿业有限公司 今日水印 相机 真实可信 MO KZGJHDPHPCYCE	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
5	提升绞车	QAJC4-BG-TSJ-0070-2025	2025 年 10 月 31 日	合格		/
6	提升绞车	QAJC4-BG-TSJ-0071-2025	2025 年 10 月 31 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
7	提升机	QAJC4-BG-TSJ-0072-2025	2025 年 11 月 1 日	合格		/
8	提升机	QAJC4-BG-TSJ-0069-2025	2025 年 10 月 30 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
9	电机车	QAJC4-BG-DJC-0017-2025	2025 年 10 月 30 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
10	电机车	QAJC4-BG-DJC-0018-2025	2025 年 10 月 31 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
11	矿用钢丝绳	QAJC4-BG-GSS-0303-2025	2025 年 10 月 29 日	合格		/


序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
12	矿用钢丝绳	QAJC4-BG-GSS-0304-2025	2025 年 10 月 29 日	合格		/
13	防坠器	QAJC4-BG-GL-0056-2025	2025 年 10 月 14 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
14	防坠器	QAJC4-BG-FZQ-0074-2025	2025 年 10 月 13 日	合格	 2025年10月13日星期一 沂南县·铜井东南村 今日水印 相机 [设备时间] ID: 3YENJ-4LM9VADN9	/
15	防坠器	QAJC4-BG-FZQ-0075-2025	2025 年 10 月 13 日	合格	 2025年10月13日星期一 沂南县·铜井东南村 今日水印 相机 [设备时间] ID: 3PNSXAVEUP6Y1	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
16	矿用钢丝绳	QAJC4-BG-GSS-0294-2025	2025 年 10 月 20 日	合格		/
17	罐笼	QAJC4-BG-GL-0057-2025	2025 年 10 月 13 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
18	罐笼	QAJC4-BG-GL-0058-2025	2025 年 10 月 13 日	合格	 2025年10月13日星期一 沂南县·铜井东南村 今日水印 相机 真实时间 设备 NH636296340291	/
19	提升机	QAJC4-BG-TSJ-0057-2025	2025 年 10 月 14 日	合格	 2025年10月14日星期二 沂南县·山东黄金矿业(沂南)有限公司 今日水印 相机 真实时间 设备 NH636296340291	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
20	提升机	QAJC4-BG-TSJ-0058-2025	2025 年 10 月 14 日	合格		/
21	提升机	QAJC4-BG-TSJ-0066-2025	2025 年 10 月 13 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
22	提升机	QAJC4-BG-TSJ-0067-2025	2025 年 10 月 13 日	合格	 时间: 2025.10.13 地点: 临沂市·铜井东南村 经纬度: 35.606239°N,118.475121°E 今日水印相机 相机: REAE-60HC-A43C3G	/
23	铲运机	QAJC4-BG-CYJ-0013-2025	2025 年 10 月 30 日	合格	 2025年10月30日 山东省，淄博市	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
24	铲运机	QAJC4-BG-CYJ-0014-2025	2025 年 10 月 30 日	合格		/
25	矿山监控系统	QAJC4-BG-JKXT-0017-2025	2025 年 10 月 30 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
26	高压开关设备	QAJC4-BG-GYKG-0873~0879-2025	2025 年 10 月 30 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
27	高压开关设备	QAJC4-BG-GYKG-0880~0881-2025	2025 年 10 月 30 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
28	电力电缆	QAJC4-BG-DL-0339~0345-2025	2025 年 10 月 31 日	合格	 	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
29	接地装置	QAJC4-BG-JDZZ-0073-2025	2025 年 10 月 30 日 -11 月 1 日	合格	 The top photograph shows a worker in a red protective suit and helmet kneeling on the ground in a tunnel, using a handheld device to test a wall-mounted electrical component. A yellow toolbox is open nearby. The bottom photograph shows two workers in red suits; one is kneeling and testing a floor-mounted device, while the other stands nearby. A red cabinet with a 'High Voltage Danger' sign is visible in the background.	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
30	高压开关设备	QAJC4-BG-GYKG-0882~0895-2025	2025 年 10 月 31 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
31	高压开关设备	QAJC4-BG-GYKG-0896~0897-2 025	2025 年 10 月 31 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
32	高压开关设备	QAJC4-BG-GYKG-0898~0908-2025	2025 年 11 月 1 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
33	电力变压器	QAJC4-BG-BYQ-0314~0322-2025	2025 年 10 月 30 日至 11 月 1 日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
					 2025.11.01 淄博市·071乡道 今日水印 相机 真实时间 设备: 44904714/1510216  2025.10.30 淄博市·071乡道 今日水印 相机 真实时间 设备: 44904714/1510216	