


序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
1	矿用钢丝绳	QAJC4-BG-GSS-0001-2026	2026年1月6日	合格	 A photograph showing a man in a red jacket and safety glasses operating a piece of industrial equipment. He is standing at a control panel with various buttons and a small screen. The background shows a white wall with a '注意安全' (Attention Safety) sign. A red bucket is on the floor to the left. A yellow watermark in the bottom right corner of the photo reads '01月06日 2026 全民水印 记录真实时间' (January 6, 2026,全民 Watermark, Record Real Time).	/
2	矿用钢丝绳	QAJC4-BG-GSS-0002-2026	2026年1月6日	合格	 A photograph showing a man in a red jacket and safety glasses operating a piece of industrial equipment. He is standing at a control panel with various buttons and a small screen. The background shows a white wall. A yellow watermark in the bottom right corner of the photo reads '01月06日 2026 全民水印 记录真实时间' (January 6, 2026,全民 Watermark, Record Real Time).	/


序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
3	矿用钢丝绳	QAJC4-BG-GSS-0003-2026	2026年1月7日	合格	 A photograph showing a worker in a red uniform with reflective stripes and a white glove operating a white industrial machine. The machine has a control panel with several buttons and a small screen. The worker is looking down at the machine. A yellow caution tape is visible on the left. A watermark in the bottom right corner of the photo reads: 01月07日 2026 星期三 全民水印 记录真实时间.	/
4	矿用钢丝绳	QAJC4-BG-GSS-0004-2026	2026年1月7日	合格	 A photograph showing a worker in a red uniform with reflective stripes and a white glove operating a large white industrial machine with its door open. Inside the machine, there are various components and tools. A yellow caution tape is visible on the left. A watermark in the bottom right corner of the photo reads: 01月07日 2026 星期三 全民水印 记录真实时间.	/


序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
5	矿用钢丝绳	QAJC4-BG-GSS-0005-2026	2026年1月7日	合格	 A photograph showing a worker from behind, wearing a red long-sleeved shirt and dark trousers, operating a control panel for a piece of industrial equipment. The equipment has a digital display and several buttons. In the background, there is a computer monitor on a desk and a yellow warning sign on the wall. A watermark at the bottom right of the photo reads "01月07日 2026 星期三 全民水印 记录真实时间".	/
6	交流电动机	QAJC4-BG-DDJ-0001~0003-2026	2026年1月8日	合格	 Two workers in red uniforms and hard hats are working on a large industrial motor. One worker is standing and appears to be operating a control panel or tool, while the other is kneeling nearby. They are in a workshop environment with various equipment and cables visible in the background. A watermark at the bottom of the photo reads "2026年01月08日星期四 我在这里 今日水印 相机自动开启".	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
7	架空乘人装置	QAJC4-BG-JKCR-0001-2026	2026年1月8日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						
8	矿用架空乘人装置	QAJC4-BG-JKCR-0002-2026	2026年1月9日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
						

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
9	交流电动机	QAJC4-BG-DDJ-0004~ 0006-2026	2026年1月8日	合格	 	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
10	矿用架空乘人装置	QAJC4-BG-JKCR-0003-2026	2026年11月8日	合格	 	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
11	矿用电缆	QAJC4-BG-DLZR-0077-2025	2025年12月31日	合格	 A photograph showing a man in a red work uniform standing next to a large industrial testing machine. The machine has a blue frame and a transparent front panel. A yellow timestamp at the bottom left of the image reads '12月31日 2025 星期三'. A watermark at the bottom right says '全民水印 记录真实时间'.	/
12	矿用电缆	QAJC4-BG-DLZR-0078-2025	2025年12月31日	合格	 A photograph showing a man in a red work uniform standing next to a large industrial testing machine. The machine has a blue frame and a transparent front panel. A yellow timestamp at the bottom left of the image reads '12月31日 2025 星期三'. A watermark at the bottom right says '全民水印 记录真实时间'.	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
13	矿用钢丝绳	QAJC4-BG-GSS-0018-2026	2026年1月8日	合格	 A photograph showing a worker in a red uniform and yellow gloves operating a white industrial machine, likely a tensile strength tester, used for inspecting steel wire ropes. The machine has a control panel with various buttons and a small screen. The worker is focused on the task. A yellow warning sign is visible in the background. A watermark at the bottom right of the photo reads: 「01月08日 2026 星期四 全民水印 记录真实时间」.	/
14	矿用钢丝绳	QAJC4-BG-GSS-0019-2026	2026年1月8日	合格	 A photograph showing a worker in a red uniform and glasses working inside a large industrial cabinet or press, likely performing a tensile test on a steel wire rope sample. The worker is wearing white gloves and is focused on the equipment. A yellow warning sign is visible in the background. A watermark at the bottom right of the photo reads: 「01月08日 2026 星期四 全民水印 记录真实时间」.	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
15	矿用钢丝绳	QAJC4-BG-GSS-0020-2026	2026年1月12日	合格		/
16	矿用钢丝绳	QAJC4-BG-GSS-0021-2026	2026年1月12日	合格		/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
17	矿用自卸汽车	QAJC4-BG-ZXQC-0001-2026	2025年1月15日	合格	 XIAOMI 15 Pro 2026.1.15	/
18	矿用自卸汽车	QAJC4-BG-ZXQC-0002-2026	2025年1月15日	合格	 XIAOMI 15 Pro 2026.1.15	/

序号	检测项目	报告编号	检测日期	检测结论	现场检测照片	备注
19	矿用自卸汽车	QAJC4-BG-ZXQC-0003-2026	2025年1月15日	合格	 <small>XIAOMI 15 Pro 2026-1-15</small>	/
20	矿用自卸汽车	QAJC4-BG-ZXQC-0004-2026	2025年1月15日	合格	 <small>XIAOMI 15 Pro 2026-1-15</small>	/